

US EPA ARCHIVE DOCUMENT

UNIT LOG	1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 10/10/2012	3. Time Prepared 1700
4. Unit Name/Designators Situation Unit	5. Unit Leader (Name and Position) Melinda Leutke, Planning Section Chief		6. Operational Period 0700, 10/04/2012 – 0700, 10/11/2012
7. Personnel Roster Assigned			
Name	ICS Position	Home Base	
Matthew Haak	Situation Unit Leader	Houston, TX	
8. Activity Log			
Time	Major Events		
0900	<ul style="list-style-type: none"> Boat safety meeting at C0.4 boat launch. Launch. C0.4 Boat Launch sheen observed. MP5.15 LDB spontaneous sheen and tar globs observed. MP5.25 LDB spontaneous sheen and tar globs observed. MP5.25 LDB spontaneous sheen and tar globs observed. MP5.35 LDB spontaneous sheen and tar globs observed. MP5.45 LDB spontaneous sheen and tar globs observed. MP5.63 LDB no sheen observed. Ceresco Dam Control Point Boom, observed the sweep boat operating. Ceresco Dam a combination of spontaneous and boat agitated sheen and tar globs observed. Ceresco Dam spontaneous sheen and tar globs observed collecting along the control point boom. MP5.55 RDB spontaneous sheen and tar globs observed. MP4.5 Below the former Island F sheen was observed. 		
12:00	<ul style="list-style-type: none"> MP15.5 South Mill Pond no sheen observed. Completed ground observations at C5 and returned to the ICP. 		
1430	<ul style="list-style-type: none"> Boarded the helicopter for the weekly overflight. Observed the source area restoration. Frac-Tank City decontamination pad, no activity observed. MP3.25 RDB sheen observed in the side channel. MP4.5 Former Island F sheen observed. MP5.0 RDB sheen observed. MP5.0 RDB sheen observed. Ceresco containment boom. MP15.5 South Mill Pond no sheen observed. MP30.8 Sediment trap sheen was observed. Morrow Lake Delta no sheen or activity observed in the delta. 		

	<ul style="list-style-type: none">• Morrow Lake no sheen or activity observed in the delta.
1600	Helicopter landed and return to ICP.
9. Prepared by (Name and Position) Matthew Haak, Situation Unit Leader, USEPA-START	